

Ripstop 690 PVC

Cleaning Instructions

PROHIBITIONS/WARNINGS

- Do not use solvents, abrasives or harsh detergents to clean.
- Do not dry clean.
- Do not iron.

GENERAL CARE INSTRUCTIONS

A regular wipe over with warm soapy water followed by rinsing with cold water will remove normal soiling. Where a build-up has occurred, the surface should be cleaned with a soft brush and mild, non-abrasive detergent, then rinsed thoroughly.

SPOT CLEANING/SPECIAL TREATMENTS

Mildew may be removed by wiping with a cold solution of household chlorine bleach having 4% chlorine, in the proportion of one part in four to water. Rinse thoroughly with cold water. We recommend testing your solution in a discrete area of the fabric, before applying to the whole area.

Use OFPANZ care label OF-1.

