

Transport Mesh 4000

Cleaning Instructions

If the surface is stained, the recommended cleaning method is to use a neutral detergent in warm water. Apply it to the surface with a soft sponge or mop and flush with sufficient water.

Solvent based cleaners should not be used. These can attack the coatings used in these materials. Abrasive cleaning agents should not be used because these can damage the top surface of the fabric.

Ensure your Transport Mesh 4000 product is completely dry before rolling or storing.

